

CORNER RECORD		Number		, Cali	fornia
City of					
Sec 32 CORNER TYPE		COOR N.	DINATES (C	Optional)	
TILN. Government Corner ☐ Control R.17 €. Meander ☐ Proper	rty 🔼	Zone NAD83 Epoch	NAD27	'□ NAD83 □	
Rancho □ Other X MDB≰ 1. Date of Survey			NGVD29 ☐ Metric ☐		
Corner – Left as found □ Found and tagged □ Es	stablished D	J Reestab	lished 🗖	Rebuilt 🗆	
O.R. P.C. TO RE-ESTABLISH THE MI					
A description of the physical condition of the monument as found and SET 5/8" REBAIZ WITH YELLOW PLASTI FOUND 1/2" REBAIR LS-2515 PER	C CAP	> 45-4	7429		
	C CAP	> 45-4	7429		
SET 5/8" REBAR WITH YELLOW PLASTICE FOUND 1/2" REBAR LS-25/5 PER PLAT SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in or the Land Surveyor's Act on August 3. Signed Math. Research P.L.Sor R.C.E. No. 7	H/MAPS	- 65 -69 68 O.R.	7429 P.C. , AS		
SET 5/8" REBAR WITH YELLOW PLASTICE FOUND 1/2" REBAR LS-25/5 PER PLAT SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in contents.	H/MAPS	- 65 -69 68 O.R.	7429 P.C. , AS	LAND SURP ATTHEW S. WEBB	

PLAT OF SURVEY LOT 9, LAKE FOREST VILLAGE, UNIT NO.1 SUBDIVISION, AS FILED IN BOOK H OF MAPS AT PAGE 68, OFFICIAL RECORDS PLACER COUNTY, CALIFORNIA. A PORTION OF SECTION 32, TOWNSHIP 16 N., RANGE 17 E., M.D.B. & M.

SCALE 1" = 50' DATE OF SURVEY 7/15/2010





NOTE:

ALL BEARINGS AND DISTANCES SHOWN HEREON ARE RECORD UNLESS NOTED PER H-MAPS-68 O.R.P.C., NO MATERIAL DISCREPANCIES WERE DISCOVERED

- FOUND MONUMENT 1/2" REBAR LS-2515, PER H-MAPS-68
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429
- O DIMENSION PT (NOTHING FOUND OR SET)

J/N 537.00